

**UNIVERSITY OF VIRGINIA
ENVIRONMENTAL HEALTH AND SAFETY**

SPECIAL MATERIALS HANDLING FACILITY
EDGEMONT ROAD
www.virginia.edu/~enhealth

P. O. BOX 400322
CHARLOTTESVILLE, VA 22904
TELEPHONE (804) 982-4911

DATE : 12-6-07

BUILDING: Montebello House

AREA(S) INSPECTED: Interior and Exterior Paints

The Office of Environmental Health and Safety has performed a minimal number of surveys for the presence of lead-based paints (LBP) within Montebello House to date, utilizing a combination of "lead-check swabs" and paint chip analyses. Generally, the results show the presence of lead on the exterior wooden trim materials, interior wooden trim materials, and the front porch columns. Not all of the painted surfaces have been tested.

A representative number of the above described paints were tested and yielded a "positive" result, which means that a paint chip analysis yielded a result of at least 0.5% lead by weight, or the check swabs detected the presence of lead, and are considered lead-based paints.

Because not all of the painted surfaces have been tested, all painted components should be assumed to contain LBP, until further testing can prove otherwise. Additionally, any paints in poor condition, described as exhibiting signs of peeling, chipping, or flaking, should be properly stabilized in accordance with Chapter 11 of the HUD guidelines entitled "Interim Controls".

Marlin Phillips
Environmental Health and Safety
Hazardous Materials Officer
Lead Risk Assessor License # 3356000860