## UNIVERSITY OF VIRGINIA ENVIRONMENTAL HEALTH AND SAFETY

SPECIAL MATERIALS HANDLING FACILITY EDGEMONT ROAD www.virginia.edu/~enhealth

P. O. BOX 400322 CHARLOTTESVILLE, VA 22904 TELEPHONE (804) 982-4911

DATE: 3-27-14 BUILDING: 121 Mimosa Drive – Farmhouse

AREA(S) INSPECTED: Interior and Exterior Paints

All paints present in the farmhouse are presumed to contain lead above the EPA's Housing and Urban Development (HUD) "action level" and shall be considered lead-based paints (LBP), until further testing proves otherwise, excluding the following paints:

- 1. The basement laundry room ceiling paint.
- 2. The wall and ceiling paints located in the first floor closets.
- 2. The kitchen cabinetry paints.

Any lead-based paints in poor condition, described as exhibiting signs of peeling, chipping, or flaking, should be properly stabilized in accordance with Chapter 11 of the HUD guidelines entitled "Interim Controls".

Marlin Phillips Environmental Health and Safety Hazardous Materials Officer Lead Risk Assessor License # 3356000860